



Auf dem Schüffel 1
D-58513 Lüdenscheid
Tel.: +49-2351 - 5542-00
Fax +49 (2351) 554-861
info@assmann-wsw.com
www.assmann-wsw.com

PRODUCT CHANGE NOTIFICATION (PCN)

ISSUE DATE: 28.11.2024
MODIFICATION / REVISION DATE: 28.11.2024

V4094 / V4433 / V4538R / V4548 / V4555 / V4718 / V5509
Mounting pads

CHANGE NOTIFICATION: PCN_20241128_MOUNTINGPADS

DESCRIPTION OF CHANGES: PRODUCT EOL - OBSOLETE

REASON FOR CHANGE: WORN OUT OF MOLD TOOLING

KEY CHARACTERISTICS OF CHANGE: Details see page 2

PRODUCTS AFFECTED: V4094 / V4433 / V4538R / V4548 / V4555 / V4718 / V5509
Mounting pads

DATE OF CHANGE AND IMPLEMENTATION: CHANGE: 48 / 2024
IMPLEMENTATION: 28.11.2024

RESPONSE: NO RESPONSE TO THIS NOTIFICATION IS REQUIRED

Auf dem Schüffel 1
D-58513 Lüdenscheid
Tel.: +49-2351 - 554-200
Fax +49 (2351) 554-861
info@assmann-wsw.com
www.assmann-wsw.com

PRODUCT CHANGE NOTIFICATION (PCN)

ISSUE DATE: 28.11.2024
MODIFICATION / REVISION DATE: 28.11.2024

V4094 / V4433 / V4538R / V4548 / V4555 / V4718 / V5509
DOCUMENT: DRAWING

ASSMANN WSW P/N	Drawing Number		ASSMANN WSW P/N	Drawing Number
V4094	ASS_0922_HSrev04	↔	OBSOLETE	OBSOLETE
V4433	ASS_3952_HSrev01	↔	OBSOLETE	OBSOLETE
V4538R	ASS_0921_HSrev04	↔	OBSOLETE	OBSOLETE
V4548	ASS_0923_HSrev04	↔	OBSOLETE	OBSOLETE
V4555	ASS_0924_HSrev05	↔	OBSOLETE	OBSOLETE
V4718	ASS_0925_HSrev04	↔	OBSOLETE	OBSOLETE
V5509	ASS_0926_HSrev04	↔	OBSOLETE	OBSOLETE